QUALITY INDICATORS

Grease-Proof Paper

Ж-30

ТУ 5452-091-00279545-2003

Ser.	Indicator name	Specification
No.		requirement
1	Paper weight with the area of 1m ² , g	30,0±1,5
2	Density, g/cm3	
	Type 1	1,0±0,05
	Type 2	1,2±0,05
3	Breakdown force, H, no less than	
	- in the machine direction	32,0
	- in the transverse direction	16,0
4	Speck counter, number of specks for 1 m ² , no	150
	more than	
5	pH of aqueous extract	5,5-9,0
6	Humidity, %, no more than	9,0

QUALITY INDICATORS

Grease-Proof Paper

Ж-23

Ser.	Indicator name	Standard
No.		
1	Paper weight with the area of 1m ² , g	23,0±1,0
2	Density, g/cm ³	
	Type 1	1,0±0,05
	Type 2	1,2±0,05
3	Breakdown force, H, no less than	
	- in the machine direction	27,0
	- in the transverse direction	14,0
4	Speck counter, number of specks for 1 m ² , no	150
	more than	
5	pH of aqueous extract	5,5-9,0
6	Humidity, %, no more than	9,0